

# Vehicle Condition Report

Brasher's Portland Auto Auction

23585 NE Sandy Blvd.  
Wood Village, OR 97060  
(503) 492-9200

All listings are subject to change without notice. Information is deemed to be reliable, but not guaranteed until announced on the auction block.

## Vehicle Description

2008 Ford F-550 No Trim Badge

VIN	1FDAX57Y78EB30926		
Ext. Color	White		
Int. Color	Tan	Interior	Vinyl
Mileage	132,396 Actual Miles		
Transmission	Manual		



## Auction Data

Sale Date	Mon - Feb 8 - <a href="#">Open to the Public</a>		
Run #	W068	Inv #	8887
Consignor	GSA FLEET SERVICES		



## Declarations

Warranty	<a href="#">GSA Regular Terms</a>
Mileage	132,396 Actual Miles
Title	Clear Title
Announcements	OIL/FLUID LEAK

## Equipment

- 2 Wheel Drive
- Trip Counter
- AM/FM Radio
- Manual Transmission
- Dual Air Bag
- Hard Top
- Air Conditioning
- Tilt Steering Wheel
- Power Steering
- Utility Bed
- Steel Wheels
- Power Brakes

## Damage Descriptions (CR completed on 12/29/2015 by Ryan Heath)

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
<b>Front</b>									
	1 Hood	Dents W/ Paint Dmg	Multiple Instances						--
<b>Front Subtotal</b>				--	--	--	--	--	--
<b>Interior</b>									
	2 Left Front Seat	Torn	4 To 5 Inches						--
<b>Interior Subtotal</b>				--	--	--	--	--	--

## 2008 Ford F-550 No Trim Badge

VIN: 1FDAX57Y78EB30926

Inv#: 8887

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
---	----------	---------------	----------	----------	----------	--------------	-------------	------------	-------

### Left



3	Left Front Fender	Dents W/ Paint Dmg	1 To 2 Inches						--
									--

#### Left Subtotal

--	--	--	--	--	--
		--	--	--	--

### Mechanical



4	Dash/Panel	Hole(S)	1 To 2 Inches						--
									--
5	Oil Pan	Multiple Dents/Paint	10 Or More						--
									--

Comment: Heavy Dmg/no Leaks

6	Transmission	Leak	Unknown						--
		Check and Advise							--

#### Mechanical Subtotal

--	--	--	--	--	--
		--	--	--	--

### Rear



7	Rear Bumper	Multiple Scratches	10 Or More						--
									--

#### Rear Subtotal

--	--	--	--	--	--
		--	--	--	--

### Right

8	Right Front Door	Multiple Scratches	10 Or More						--
									--



9	Right Qtr Panel	Dents W/ Paint Dmg	> 12 Inches						--
									--

#### Right Subtotal

--	--	--	--	--	--
		--	--	--	--

#### Total

--	--	--	--	--	--
		--	--	--	--

### Tires

Region	Brand	Size	Tread Depth
Left Front	MATCHED	/-	Average (Average)
Left Rear	MATCHED	/-	Average (Average)
Right Front	MATCHED	/-	Average (Average)
Right Rear	MATCHED	/-	Average (Average)

## 2008 Ford F-550 No Trim Badge

VIN: 1FDAX57Y78EB30926

Inv#: 8887

### Miscellaneous

Interior odor

Foul

### Images



## 2008 Ford F-550 No Trim Badge

VIN: 1FDAX57Y78EB30926

Inv#: 8887

---

